



Figure 14: View of industrial area and railway track

R F Burden



Figure 15: Church View development

R F Burden

Figure 15 shows the relatively new development of Church View. The houses are adjacent to the Chantry Fields site, with several access points. The impact of the recent buildings is reduced, but not removed, by the softening effect of the substantial hedges. The large trees both around the development and within it help to soften the hard edges. There is a storm water retention area in the mid-ground, however this is not visible here due to the long vegetation.

Figure 16 is the view from Stour Meadows towards the Brickfields Business Park. Additional tree planting in the mid-distance may help to soften the impact, which is partly reduced by the existing tree planting on the railway bank. This may be achieved by the proposed cemetery, as long as it is well positioned on the slope.



Figure 16: View from Stour Meadows

R F Burden