

## **Bournemouth, Dorset and Poole Mineral Sites Plan – Inspector Site Visit**

**Wednesday 10<sup>th</sup> October 2018**

9:00 Collect programme officer, Bere Regis

9:30 Collect Inspector, Thistle Hotel, The Quay, Poole

10:15 Park at the Lookout/Afflington Lookout Barn. Meet two residents - opportunity to walk the Purbeck Way.

11.15 (approximate time) Return to Swanworth Quarry to view a quarry blast.

12:00 Depart Swanworth Quarry for Wareham train station.